


Contact-state ambiguity and online correction during latch flipping

(a) VLA (π0.5) — Failure







(b) TORL-VLA Online Correction — Success

